



4448 Sisk Road - Modesto, CA 95356
 Phone: (209) 545-6155 • Fax: (209) 545-6152

Compare Fabric Structures to Traditional Metal Buildings		
Poly Structure		Metal/Wood Building
✓	No columns or poles on interior; maximize useable space	✗
✓	Maintains shape and does not warp, swell or rot away	✗
✓	Steel frame does not rust even in the harshest conditions	✗
✓	Corner-free nature and absence of insulation keeps pest free environment	✗
✓	Flame resistant material available, less likely to catch on fire	✗
✓	Able to withstand natural weather events, lower insurance costs	✗
✓	Exceptional acoustics, minimize sound of rain and sleet	✗
✓	Abundant interior sunlight during the day, reduce energy bills	✗
✓	Building stays warmer in winter, cooler in summer; climate control	✗
✓	Ventilation option, interior smells fresher, eliminates moisture & bacteria	✗
✓	Never needs painting; rain washes off dust, dirt & pollutants	✗
✓	Low cost per square foot	✗
✓	Quick to build, construction costs less	✗
✓	Buildings can be moved or taken down, easy to add onto	✗